

Audi	A5 Avant	09/24>
Audi	A6 Allroad	03/12>10/14
Audi	A6 Allroad	06/06>02/12
Audi	A6 Allroad	11/14>08/19
Audi	A6 Avant	03/05>08/11
Audi	A6 Avant	04/16>07/18
Audi	A6 Avant	07/01>02/05
Audi	A6 Avant	08/94>07/97
Audi	A6 Avant	08/97>06/01
Audi	A6 Avant	09/11>10/14
Audi	A6 Avant	11/14>03/16
Audi	Allroad	06/00>05/06
Bmw	Serie 3 Gran Turismo (F34)	04/13>06/16
Bmw	Serie 3 Gran Turismo (F34)	07/16>12/20
Bmw	Serie 5 Touring (E39)	04/97>08/00
Bmw	Serie 5 Touring (E39)	09/00>03/04
Bmw	Serie 5 Touring (E61)	04/04>05/10
Bmw	Serie 5 Touring (F11)	06/10>06/13
Bmw	Serie 5 Touring (F11)	07/13>03/17
Bmw	Serie 5 Touring (G31)	04/17>07/20
Bmw	Serie 5 Touring (G31)	08/20>02/24
Citroen	C5 Tourer	05/08>07/12
Citroen	C5 Tourer	08/12>12/17
Citroen	C5 X 5p	11/21>
Citroen	C5 sw	03/01>04/08
Ferrari	GTC4 Lusso 2p	09/16>10/20
Ford	Mondeo Hybrid	03/19>02/22
Ford	Mondeo Hybrid	11/14>02/19
Ford	Mondeo Wagon	03/19>02/22

Ford	Mondeo Wagon	05/07>09/10
Ford	Mondeo Wagon	10/10>10/14
Ford	Mondeo Wagon	11/14>02/19
Ford	Mondeo sw	01/01>04/07
Ford	Mondeo sw	10/96>12/00
Honda	Accord Tourer	04/03>06/08
Hyundai	i40 Wagon	07/11>06/15
Hyundai	i40 Wagon	07/15>08/19
Jaguar	XF Sportbrake	01/21>08/24
Jaguar	XF Sportbrake	08/17>12/20
Jaguar	XF Sportbrake	11/12>11/16
Kia	Optima Sportwagon	10/16>12/19
Kia	ProCeed Shooting Brake	03/19>09/21
Kia	ProCeed Shooting Brake	10/21>
Lancia	K sw	06/96>12/01
Lancia	Thema sw	11/84>12/94
Lexus	RZ	07/23>
Mazda	6 Wagon	11/18>12/22
Mercedes	Classe C sw	06/21>05/23
Mercedes	Classe C sw	06/23>
Mercedes	Classe E sw	03/03>08/09
Mercedes	Classe E sw	03/13>11/16
Mercedes	Classe E sw	05/96>02/03
Mercedes	Classe E sw	09/09>02/13
Mercedes	Classe E sw	09/20>10/23
Mercedes	Classe E sw	11/23>
Mercedes	Classe E sw	12/16>08/20
Nio	ET5 Touring	09/23>
Opel	Astra L Sports Tourer	03/22>

Opel	Insignia Country Tourer	04/20>08/22
Opel	Insignia Country Tourer	10/17>03/20
Opel	Insignia Country Tourer	11/13>04/17
Opel	Insignia Sports Tourer	03/09>10/13
Opel	Insignia Sports Tourer	04/20>08/22
Opel	Insignia Sports Tourer	05/17>03/20
Opel	Insignia Sports Tourer	11/13>04/17
Opel	Omega sw	06/94>12/03
Opel	Vectra sw	01/04>02/09
Peugeot	308 sw	09/21>
Peugeot	406 sw	04/99>02/05
Peugeot	508 Rxh	05/12>08/14
Peugeot	508 Rxh	09/14>05/17
Peugeot	508 sw	01/19>03/23
Peugeot	508 sw	03/11>08/14
Peugeot	508 sw	04/23>
Peugeot	508 sw	09/14>05/18
Renault	Laguna III Sportour	05/13>06/16
Renault	Laguna III Sportour	10/07>04/13
Renault	Talisman Sporter	06/16>12/22
Renault	Vel Satis	04/02>12/09
Saab	9-5 sw	01/01>08/10
Seat	Leon Sportstourer	06/20>
Skoda	Octavia Wagon	03/24>
Skoda	Octavia Wagon	06/20>02/24
Skoda	Superb Wagon	02/10>08/13
Skoda	Superb Wagon	04/24>
Skoda	Superb Wagon	09/13>09/15
Skoda	Superb Wagon	09/19>12/23

Skoda	Superb Wagon	10/15>08/19
Subaru	Legacy Station Wagon	01/99>04/03
Subaru	Legacy Station Wagon	05/03>08/09
Volkswagen	Passat Variant	12/23>
Volvo	V60	05/13>08/18
Volvo	V60	09/18>
Volvo	V60	11/10>04/13
Volvo	V60 Cross Country	05/15>10/18
Volvo	V60 Cross Country	11/18>04/25
Volvo	V70 sw	01/00>04/07
Volvo	V70 sw	05/07>04/13
Volvo	V70 sw	05/13>09/16
Volvo	V90 Cross Country	04/20>
Volvo	V90 Cross Country	09/16>03/20
Volvo	V90 sw	04/20>
Volvo	V90 sw	09/16>03/20
Volvo	XC70 sw	01/00>04/07
Volvo	XC70 sw	05/07>04/13
Volvo	XC70 sw	05/13>09/16